

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 23 12 00 PM '69

| |
|--|
| 5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. B-9953 |
| 7. Unit Agreement Name |
| 8. Farm or Lease Name No. Anderson Ranch Unit |
| 9. Well No. 4 |
| 10. Field and Pool, or Wildcat Anderson Ranch Wlfc., No. |
| 12. County Lea |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| |
|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Union Oil Company of California 3. Address of Operator P. O. Box 671; Midland, Texas 79701 4. Location of Well UNIT LETTER I 2310 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 15-S RANGE 32-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4315' GR |
|---|

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

| | |
|--|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> |

SUBSEQUENT REPORT OF:

| | |
|--|---|
| REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set Bridge plug at 9850' and cap with 20' cement.
Cut and pull 4-1/2" casing from free point.
Spot cement plugs as follows:

35 sx. - in and out of 4 1/2" casing stub,
35 sx. - top of bone springs - 6950',
35 sx. - top of San Andres - 4944',
40 sx. - in and out of 8-5/8" casing at 4116'.
Cut and pull 8 5/8" casing from free point.
35 sx. - in and out of 8-5/8" casing stub,
50 sx. - 700' - 550',
10 sx. - surface - 30'.

Weld plate on 11-3/4" casing, install dry hole marker and clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.G. Ladd, Jr. TITLE District Drilling Supt. DATE August 21, 1969
APPROVED BY [Signature] TITLE [Signature] DATE AUG 25 1969
CONDITIONS OF APPROVAL, IF ANY: