

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 300250036700
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9683
7. Lease Name or Unit Agreement Name Anderson Ranch Unit
8. Well No. 17
9. Pool name or Wildcat Anderson Ranch Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Conoco, Inc.	
3. Address of Operator 10 Desta Dr Ste 100W, Midland, TX 79705-4500	
4. Well Location Unit Letter <u>R 3</u> : 1980 Feet From The <u>South</u> Line and 1980 Feet From The <u>East</u> Line Section <u>2</u> Township <u>16-S</u> Range <u>32-E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 4278'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to add perfs to and acidize this well in the Upper Wolfcamp Hueco zone by the following procedures:

1. Run bit and scraper to clean out to 9640'.
2. Set RBP @ 9620'
3. Perforate with 256 shots from 9450' to 8954'.
4. Acidize with 4,000 gallons 15% NEFE HCl.
5. Put back on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gerry W. Hoover TITLE Sr. Conservation Coordinator DATE June 25, 1991

TYPE OR PRINT NAME Gerry W. Hoover TELEPHONE NO. (915) 686-6548

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: