## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Report by Checkin	g Below		
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	x	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	
	October 29, 1954 (Date)	<b>.</b>	Hobbs, New M	exico
Following is a report on the work	done and the results obtained under the head	ding noted	d above at the	
Continental Oil Compa	Ar erator)	ndersor	Ranen Init	
(Contractor			(Unit R)	
168 , R32E , NMPM , And	erson Ranch-Wolfcamp Pool,		es	Count
he Dates of this work were as folows:	10-27-54			
lotice of intention to do the work (was	) (was not) submitted on Form C-102 on			, 19
		(Cr	oss out incorrect words)	
nd approval of the proposed plan (was	(was not) obtained.			
and approval of the proposed plan (was	, (was not) obtained:			
• • • • • • •		TRETT M	COPADIED	
• • • •	LED ACCOUNT OF WORK DONE AND F	RESULTS	S OBTAINED	
• • • •		RESULTS	S OBTAINED	
DETAI	LED ACCOUNT OF WORK DONE AND I			9
Set 8 5/87 OD ca	LED ACCOUNT OF WORK DONE AND F	2415 au	soke sement, using l	
Set 8 5/87 OD ca	LED ACCOUNT OF WORK DONE AND I	2415 au	soke sement, using l	
DETAI Set 8 5/87 OD ca entralizers and 95 scratc	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	ncke sement, using l Sk. Cement circula	
DETAI Set 8 5/87 OD ca entralizers and 95 sorato Tested casing wi	LED ACCOUNT OF WORK DONE AND F	2415 ac 10-27	ncke sement, using l Sk. Cement circula	
DETAI Set 8 5/87 OD ca entralizers and 95 sorato Tested casing wi	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	ncke sement, using l Sk. Cement circula	
DETAI Set 8 5/87 OD ca entralizers and 95 sorato Tested casing wi	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	ncke sement, using l Sk. Cement circula	
DETAI Set 8 5/87 OD ca entralizers and 95 sorato Tested casing wi	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	ncke sement, using l Sk. Cement circula	
DETAI Set 8 5/87 OD ca entralizers and 95 scratc Tested casing wi	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	acks sement, using l Sk. Cement circula	
DETAI Set 8 5/87 OD ca atralizers and 95 scratc Tested casing wi	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	acks sement, using l Sk. Cement circula	
DETAI Set 8 5/87 OD ca entralizers and 95 scratc Tested casing wi	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	acks sement, using l Sk. Cement circula	
DETAI Set 8 5/87 OD ca entralizers and 95 scratc Tested casing wi	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	acks sement, using l Sk. Cement circula	
DETAI Set 8 5/87 OD ca atralizers and 95 scratc Tested casing wi	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	acks sement, using l Sk. Cement circula	
DETAI Set 8 5/87 OD ca entralizers and 95 scratc Tested casing wi	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	acks sement, using l Sk. Cement circula	
Set 8 5/87 OD ca entralizers and 95 scratc Tested casing wi ressure drop.	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	acks sement, using l Sk. Cement circula	
Set 8 5/87 OD ca atralizers and 95 scratc Tested casing wi ressure drop.	sing at 41961, comented with 2 hers. Plug down at 4:15 A.M.	2415 ac 10-27	acks sement, using l Sk. Cement circula	
Set 8 5/87 OD ca entralizers and 95 scratc Tested casing wi ressure drop.	sing at 4196°, community with 2 hero. Plug down at 4:15 A.M. th 1500% pressure before and a	2415 ac 10-27	ecks sement, using li-54. Coment circula Erilling plug. No	
Set 8 5/87 OD cantralizers and 95 sorate  Tested casing with ressure drop.  Witnessed by	sing at 4196, cemented with 2 hero. Plug down at 4:15 A.M. th 1500/ pressure before and a (Company)	2415 at 10-27-	ceke sement, using life, Cement circularitilling plug. No	ted.
Set 8 5/87 OD cantralizers and 95 sorate  Tested casing with ressure drop.  Witnessed by	sing at 4196, cemented with 2 hero. Plug down at 4:15 A.M. th 1500/ pressure before and a (Company)	2415 at 10-27-	ceke sement, using life, Cement circularitilling plug. No	ted.
Set 8 5/87 OD cantralizers and 95 scratcantralizers and 95 scratcantral	sing at 4196, cemented with 2 hero. Plug down at 4:15 A.M. th 1500/ pressure before and a (Company)	2415 at 10-27-	ceke sement, using life, Cement circularitilling plug. No	ted.
Set 8 5/87 OD cantralizers and 95 scratcantralizers and 95 scratcantral	sing at 4196, cemented with 2 hers. Plug down at 4:15 A.M.  th 1500f pressure before and a (Company)  COMMISSION  I hereby cert to the best of Name	ify that the firmy known of the control of the cont	(Title)	ue and comple
Set 8 5/87 OD cantralizers and 95 scratcantralizers and 95 scratcantral	sing at 4196°, comented with 2 hers. Plug down at 4:15 A.M.  th 1500% pressure before and a commission  (Company)  I hereby cert to the best of Name	ify that the my known is the standard of the s	(Title)  (Title)  (Title)  (Title)	ue and comple
Set 8 5/87 OD cantralizers and 95 sorate  Tested casing with ressure drop.  Witnessed by	sing at 4196, cemented with 2 hers. Plug down at 4:15 A.M. th 1500// pressure before and a commission  (Company)  COMMISSION  I hereby cert to the best of the best of the commission	ify that the first waste. It	(Title)	ue and comple