

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-00375

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
NM 2979

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ GAS Well ☐ OTHER ☐

2. Name of Operator
Blanco Engineering, Inc.

3. Address of Operator
P.O. Box 298, Artesia, NM 88210

7. Lease Name or Unit Agreement Name

New Mexico "S"

8. Well No. 1

9. Pool name or Wildcat
No. Anderson Ranch Wolfcamp

4. Well Location
Unit Letter B : 1650 Feet From The East Line and 990 Feet From The North Line
Section 2 Township 16S Range 32E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4297 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is the intention of Blanco Engineering, Inc. to set 7 5/8" CIBP at 9650' over perforations 9706-10. Place 50 sx cement plug on top of CIBP. Attempt to recover 7 5/8" casing from 7565 to surface. Place 100 sx cement in and above 7 5/8" cut off. Place 100 sx cement plug at base of 9 5/8" casing at 4122. Place 50 sx plug at 2393 (base of salt) and 50 sx cement plug at 1390 (top of salt). Place 50 sx cement plug at 350' inside 9 5/8" casing. Place 10 sx cement plug in top of 9 5/8" casing. Clean up all pits, fencing and well location. Prepare area for inspection by NMOCC. will notify NMOCC 24 hours prior to P & A operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paul White TITLE Engineer DATE 12/5/95

TYPE OR PRINT NAME PAUL G. WHITE TELEPHONE NO. _____

ORIGINAL SIGNED BY JEFF TEXON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

DEC 08 1995

