

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-00379
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Aggie - A
2. Name of Operator Penrod Oil Corp.	8. Well No. 1
3. Address of Operator PO Box 5970 Hobbs, NM 88241	9. Pool name or Wildcat Anderson Arch Wellcamp
4. Well Location Unit Letter Q : 600 Feet From The East Line and 1978 Feet From The South Line Section 3 Township 16 S Range 32 E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4336' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. **5-13-96**

Plans are To Rig Up Pulling Unit
Set CIBP ± 9700' & Cap w/ 35 SX Cmt.
Freeport & Cut 5 1/2" Csg. at ± 8500'
Set 50 SX Cmt (50' in 50' Out) at 5 1/2" Csg. Stub
Set 50 SX Cmt (50' in 50' Out) at 8 3/4" Csg. Shoe (4210')
Set 50 SX Cmt (50' in 50' Out) at 13 3/8" Csg. Shoe (436')
Set 10 SX Cmt at Surface
Install Day Hole Marker
Clean Location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Y. (Merch) Merchant TITLE President DATE May 10, 1996
TYPE OR PRINT NAME M. Y. (Merch) Merchant TELEPHONE NO. (505) 397-3596

(This space for State Use) ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 13 1996

