

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan, as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL <b>Well to Abandon</b>	<b>X</b>	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

**Hobbs, New Mexico**

(Place)

**October 18, 1954**

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the

**State Q-15**

**Continental Oil Company**

(Company or Operator)

Well No. **1** in **G**

(Unit)

**SW NE 1/4 of Sec. 15, T. 16S, R. 32E, NMPM, Anderson Ranch-Penn. Pool**  
(40-acre Subdivision)  
**Lea** County.

FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

**It is proposed to plug and abandon this well as follows:**

- (1) Pull tubing and set 100' cement plug from 12,331' to T.D. of 12,431'.
- (2) Shoot off 7" casing at approximately 7700'.
- (3) Fill hole with 12# mud to a point 50' below where 7" casing is shot off.
- (4) Set a 100' cement plug from approximately 7650' to 7750'.
- (5) Fill hole with 12# mud to a point 50' below 9 5/8" casing shoe which is set at 4221'.
- (6) Set 100' cement plug from 4171' to 4271'.
- (7) Fill hole with 12# mud to a point 50' below the surface.
- (8) Set 50' cement plug with 4" marker inside of 13 3/8" casing.
- (9) Restore location to its original condition.

Approved....., 19.....  
Except as follows:

Approved  
OIL CONSERVATION COMMISSION

By **J. G. Stanley**  
Title.....

**Continental Oil Company**

(Company or Operator)

By.....

Position **District Superintendent**

Send Communications regarding well to:

Name **Continental Oil Company**

Address **Box 427, Hobbs, New Mexico**