

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED
MAY 10 1975

1. OIL WELL GAS WELL OTHER **Injection Well**

2. NAME OF OPERATOR **Artec Oil & Gas Co.**

3. ADDRESS OF OPERATOR **P. O. Box 837, Hobbs, New Mexico 88240**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
Unit Letter F, 1980' from the north line and 2240' from the west line, section 31, township 15 range 32.

14. PERMIT NO. _____

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4112 GR

5. LEASE DESIGNATION AND SERIAL NO.
NM 0900

6. IF INDIAN, ALLOTTEE OR TRIBE NAME _____

7. UNIT AGREEMENT NAME
ROBINSON UNIT

8. FARM OR LEASE NAME
ROBINSON UNIT TR. 2-31

9. WELL NO.
6

10. FIELD AND POOL, OR WILDCAT
Malj. Graby, S.S.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
d 31-16S-32

12. COUNTY OR PARISH
Loa

13. STATE
N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set 4 1/2" BP @ 3750'.
2. Dump 4 sx. cement on top.
3. Spot 25 sx. plug @ 2500'.
4. Spot 35 sx. plug @ 500'.
5. Spot 35 sx. plug @ 550', 4 1/2" cut off.
6. Spot 50 sx. plug @ 250'.
7. Spot 10 sx. plug @ surface.
7. Install dry-hole marker and clean location.
Hole loaded w/mud and plugs displaced with mud.
8. Date abandoned - 4-24-75.

18. I hereby certify that the foregoing is true and correct

SIGNED *Ray Baker* TITLE AGENT DATE 5/2/75

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: