

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use APPLICATION FOR PERMIT for such proposals.

5. LEASE DESIGNATION AND SERIAL NO.

NM-016804

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Robinson Unit Tr. 1

9. WELL NO.

3

10. FIELD AND POOL OR WILDCAT

Maljamar GB-SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 31 T16S R32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

1. NAME OF OPERATOR

Dwight A. Tipton

2. ADDRESS OF OPERATOR

P. O. Box 755, Hobbs, New Mexico 88241

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below)

At surface 990' FNL & 1730' FWL of Sec. 31

14. PERMIT NO.

17. ELEVATIONS (Show whether DF, RT, GR, etc.)

4130

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

SUBSEQUENT REPORT OF:

TEST WATER SHUT OFF

PULL OR ALTER CASING

WATER SHUT OFF

REPAIRING WELL

FRACURE TREAT

WELL LIFT CONDUIT

FRACURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Initial)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

18. IF WELL IS PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well plugged as per instructions from Ralph Dillowas follows:

Work began 11/18/85. Spot 15 sack cement plug thru tubing 3250 to 3500. Pull tubing. Perforate 4 1/2" casing with 2 shots at 2100. Ran tubing open ended, spot 25 sack plug 1800 to 2100. Pulled and layed down tubing. Put on well head flange, closed 4 1/2" casing valve, open 8 5/8" casing valve, pumped cement down 4 1/2" casing & circulated back to surface with 39 barrels cement. Closed bradenhead valve & squeezed 24 barrels cement into well. Closed in wellhead. WOC 24 hours. Tag top cement 25' down in 4 1/2" casing, at surface in 8 5/8" casing. Install dry hole marker. Work completed 11/20/85. Location is ready for inspection.

19. I hereby certify that the foregoing is true and correct

SIGNED

Donna Halls

TITLE Agent

DATE 1/15/86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

9-28-88

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well and
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

m

RECEIVED

SEP 29 1988

OCD
HOBBS OFFICE