

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 023419
7. Lease Name or Unit Agreement Name Robinson Unit Tract 3
8. Well No. 31-11
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Dwight A. Tipton
3. Address of Operator 1800 North Main, Lovington, NM 88260	4. Well Location Unit Letter _____ : 1980 Feet From The South Line and 1650 Feet From The West Line Section 31 Township 16-S Range 32-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Spot 40 sacks cement Plug @ 4030' W.O.C. Tag cement top @ 3641'
- 2) Load hole with mud
- 3) Perforate 4½ casing @ base of salt 2071' unable to pump into perforations Spot 25 sacks cement @ 2121' across perforations
- 4) Perforate 4½ casing @ 8-5/8 shoe 380' Squeeze with 50 sacks cement W.O.C. did not tag cement Respot 60 sacks cement W.O.C. Tag cement top @ 262'
- 5) Perforate 4½ casing @ 50' circulate cement to surface between 4½ & 8-5/8 leaving 4½ full Set PA marker
- 6) Job completed 1-8-96

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE E. Leica Klock TITLE District Secretary DATE 1-11-96  
TYPE OR PRINT NAME Dwight A. Tipton TELEPHONE NO. 505-396-2114

(This space for State Use)

APPROVED BY Tammy W. Hill TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: