

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-81

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-00420

5. Indicate Type of Lease

STATE ☒ FE

6. State Oil & Gas Lease No.  
023419

7. Lease Name or Unit Agreement Name

Robinson Unit Tract 3

8. Well No.

31-11

9. Pool name or Wildcat

Maljamar GB/SA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OR

WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

Dwight A. Tipton

3. Address of Operator

1800 North Main - Lovington, New Mexico 88260

4. Well Location

Unit Letter

K

: 1980

Feet From The South

Line and

1650

Feet From The

W

Section

31

Township

16-S

Range

32-E

NMPM

Lea

Cou

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMEN

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Spot 30 sacks of cement plug from TD 4030 to 3730' and tag
- 2) Load hole W/mud
- 3) Perferate 4 1/2 casing 50' below base of salt at 2071' squeeze W/30 sacks cement below packer and W.O.D. tag cement top at 1971
- 4) Perferate 4 1/2 casing 50' below 8 5/8 shoe at 380' squeeze 30 sacks cement below packer and W.O.C. tag cement top at 380'
- 5) Perferate 4 1/2 casing at 50' circulate cement to surface between 4 1/2 and 8 5/8 casing leaving 4 1/2 full
- 6) Set P.A. Marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Raymond Maldonado

TITLE

Supervisor

DATE

6-19-95

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

BY JERRY SEXTON SUPERVISOR

APPROVED BY

TITLE

DATE

JUN 19 1995

CONDITIONS OF APPROVAL IF ANY

RECEIVED

27 1995

U.S. DEPARTMENT OF JUSTICE  
FEDERAL BUREAU OF INVESTIGATION

2001 4 1 11:11