Form Approved. Budget Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

5. LEASE
Federal NM 0315712
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
Maljamar Grayburg Unit
8. FARM OR LEASE NAME
Maljamar Grayburg Unit
9. WELL NO.
26
10. FIELD OR WILDCAT NAME
Maljamar (Grayburg-San Andres)
11. SEC., T., R., M., OR BLK. AND SURVEY OF
AREA
Sec. 4, T-17-S, R-32-E
12. COUNTY OR PARISH 13. STATE
Lea NM
14. API NO.
NA

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use form 9-331-C for such proposals.) 1. oil gas other Water Injection 2. NAME OF OPERATOR Chevron USA, Inc. 3. ADDRESS OF OPERATOR P.O. BOX 1660 Midland, Texas 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit N, 660' FSL, 2310' FWL AT TOTAL DEPTH: 4030' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE FRACTURE TREAT SHOOT OR ACIDIZE PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly State all pertinent details, and give pertinent data including estimated date of starting any proposed work. Fivel is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones forkinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH W/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'. 4) Spot sand on RBP. Set pkr. @ 571'. M&P 200 sx. Class "C" cmt.
COO not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals. 1. oil
1. cil gas well other Water Injection 2. NAME OF OPERATOR Chevron USA, Inc. 3. ADDRESS OF OPERATOR P.O. Box 1660 Midland, Texas 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit N, 660' FSL, 2310' FWL AT TOP PROD. INTERVAL: 3844' AT TOTAL DEPTH: 4030' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL
1. Well Well other Water Injection 26 10. FIELD OR WILDCAT NAME 10. FIELD OR WILDCAT NAME 10. FIELD OR WILDCAT NAME 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA 12. COUNTY OR PARISH 13. STATE 13. STATE 14. API NO. 14. API NO. 15. ELEVATIONS (SHOW DF. KDB. AND WE GREAT WELL 15. SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF 15. SUBSEQUENT REPORT OF: TEST WATER ALTER CASING 15. SEC. SEC. SEC. SEC. SEC. SEC. SEC. SEC
2. NAME OF OPERATOR Chevron USA, Inc. 3. ADDRESS OF OPERATOR P.O. Box 1660 Midland, Texas 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit N, 660' FSL, 2310' FWL AT TOP PROD. INTERVAL: 3844' AT TOTAL DEPTH: 4030' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF
Chevron USA, Inc. 3. ADDRESS OF OPERATOR P.O. Box 1660 Midland, Texas 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit N, 660' FSL, 2310' FWL AT TOP PROD. INTERVAL: 3844' AT TOTAL DEPTH: 4030' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF
3. ADDRESS OF OPERATOR P.O. Box 1660 Midland, Texas 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit N, 660' FSL, 2310' FWL AT TOP PROD. INTERVAL: 3844' AT TOTAL DEPTH: 4030' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF GRACIUZE
P.O. Box 1660 Midland, Texas 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit N, 660' FSL, 2310' FWL AT TOP PROD. INTERVAL: 3844' AT TOTAL DEPTH: 4030' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL COMPLETE CHANGE ZONES ABANDON' (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data including estimated date of starting any proposed work. If yell is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pretinent to this work.)* 18. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Sec. 4, T-17-S, R-32-E 19. COUNTY OR PARISH 13. STATE Lea NM 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND W GR 4101' 16. CHECK APPROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data including estimated date of starting any proposed work. If yell is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pretinent to this work.)*
below.) AT SURFACE: Unit N, 660' FSL, 2310' FWL AT TOP PROD. INTERVAL: 3844' AT TOTAL DEPTH: 4030' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE PALL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data including estimated date of starting any proposed work. If yell is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones partinent to this work.)* 18. ELEVATIONS (SHOW DF, KDB, AND W GR 4101' 19. ELEVATIONS (SHOW DF, KDB, AND W GR 4101' 10. MIRU PU. NOTE: Report results of multiple completion or zone partinent data including estimated date of starting any proposed work. If yell is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones partinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/BP & pkr. Test csg. Found hole between 787'-911'.
AT SURFACE: Unit N, 660' FSL, 2310' FWL AT TOP PROD. INTERVAL: 3844' AT TOTAL DEPTH: 4030' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones partinent to this work.)* 17. MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/BP & pkr. Test csg. Found hole between 787'-911'.
AT TOP PROD. INTERVAL: 3844' AT TOTAL DEPTH: 4030' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF SHOOT OR ACIDIZE SHOOT OR ALTER CASING SHOWLITIPLE COMPLETE SHOOT OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
AT TOTAL DEPTH: 4030' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND W GR 4101' 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, NATURE OF NOTICE, NATURE OF NOTICE, NATURE OF NOTICE, STATE OF SUBSEQUENT REPORT OF: 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent date including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)* 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent date including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)*
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND W GR 4101' REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pretinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
PULL OR ALTER CASING
MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones remainent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. C0 to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. C0 to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
including estimated date of starting any proposed work livel is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
including estimated date of starting any proposed work livel is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)* 1) MIRU PU. NDWH. NUBOP. POOH w/tbg. 2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
2) RIH w/bit & scraper. CO to 3948'. 3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
3) RIH w/RBP & pkr. Test csg. Found hole between 787'-911'.
/) Seet and on PRP Set ply 0 571' M&P 200 ev Class "C" cmt
4) Spot sand on RBP. Set pkr. @ 5/1'. M&P 200 Sx. Class C cmt
w/5#/sx Koalite & 2% CaCl; tail-in w/50 sx Class "C" cmt. , Sqz. to
standing pressure of 600 psi. WOC 9:45 AM
5) Tag T/ont 0 706' DOC to 877' RIH to 1022'. Test to 600 psi.& Would.
not hold. Check csg. for other leaks. Found leak @ 368'±,525'±, 800'
6) Set RBP @ 760' & set pkr. @ 350'. M&P w/120 sx Class "C". WOC
7) DOC to 882'. Test csg to 500 psi. Held OK. Retrieve RBP.
8) Acidize w/2400 gals. 15% NEFE HCL. Swab well.
9) RIH w/inj. pkr. Set @ 3702'. Pump pkr. fluid. Test to 500 psi. Put on inj
Subsurface Safety Valve: Manu. and Type Set @
18. I hereby certify that the foregoing is true and correct
SIGNED TITLE Eng. Asst. DATE 2-26-85

MAR 1 1985

*See Instructions on Reverse Side

RECEIVED

•

MAR -4 1985

HOST CARE