

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT TO: N.M.C. Cons. Division
1625 N. French Dr.
Hobbs, NM 88240
Budget Bureau No. 1004-0135
Expires August 31, 1985

1. SIGNATURE AND SERIAL NO.
NM-0315712

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P & A	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR The Wiser Oil Company	7. UNIT AGREEMENT NAME Maljamar Grayburg
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241	8. API No. 30-025-00461
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2310' FSL & 330' FWL Unit L	9. WELL NO. 23
	10. FIELD AND POOL, OR WILDCAT Maljamar Grayburg San Andres
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 4-T17S-R32E
14. PERMIT NO	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4118' GL
	12. COUNTY OR PARISH Lea County
	13. STATE N.M.

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input checked="" type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT * <input type="checkbox"/>
(Other) _____	
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Wiser Oil requests approval to Plug and Abandon the well by the procedure listed below.

SURFACE CASING: 8-5/8" set @ 297'. PRODUCTION CASING: 5-1/2" set @ 4024'
PERFORATIONS: 3814'-3980'

1. Tag cement plug @ surface.
2. Drill cement down to 1030'.
3. Run cement bond log to find cement top.
4. Perforate csg. above cement top & circulate cement to surface.
5. Tag cement top in csg. if cement is not at surface in 5-1/2" csg.
6. Set 50' cement plug @ surface if not already at surface.
7. Install dry hole marker
8. Clean location.

18. I hereby certify that the foregoing is true and correct.

SIGNED G. M. Jones TITLE Superintendent DATE February 27, 2001

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) DAVID R. GLASS

TITLE PETROLEUM ENGINEER

DATE MAR 20 2001

CONDITIONS OF APPROVAL, IF ANY:

*See Instruction On Reverse Side

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

GWW