Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPLIC Other Instructions DEPARTMENT THE INTERIOR Verse side)		
	GEOLOGICAL SURVEY	NM 0315712	
		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
(Do not u	SUNDRY NOTICES AND REPORTS ON WELLS use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)		
1.		7. UNIT AGREEMENT NAME	
	WELL OTHER Water Injection Well	Maljamar (Grayburg)	
2. NAME OF OPER		8. FABM OR LEASE NAME	
Chevron 3. Address of 0		9. WELL NO.	
	x 1660, Midland, Texas 79701 SEP 25 197		
	well (Report location clearly and in accordance with any State requirements." e 17 below.) U. S. GEOLOGICAL SI	10. FIELD AND FOOL, OF WILDCAT Maljamar Gravburg-San Andres	
	HOBBS, NEW MEX	SURVEI OR AREA	
Unit B,	330' FNL & 1980' FEL, Section 9, T-17-S, R-32-E	Section 9, T-17-S, R-32-E, NMPM 12. COUNTY OF PARISH 13. STATE	
14. PERMIT NO.			
	<u> </u>	Lea New Mexico	
16.	Check Appropriate Box To Indicate Nature of Notice, Report	, or Other Data	
	NOTICE OF INTENTION TO:	UBSEQUENT REPORT OF:	
TEST WATER	BHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TR			
SHOOT OR AC		IG ABANDONMENT [•] X	
CEPAIR WELL (Other)	(NOTE : Report	results of multiple completion on Well ecompletion Report and Log form.)	
17. DESCRIBE PROP	FOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent work. If well is directionally drilled, give subsurface locations and measured and true	dates, including estimated date of starting any	
8-23-75	Dug pit. Move in rig up pulling unit.		
	8-25-75 Pulled out of hole with tubing. Ran in hole with tubing to 3700'. Attempted to circulate hole with mud laden fluid with out success. Spotted 25 sacks cement, pulled tubing.		
8-26-75 Ran tubing and tagged cement at 3510'. Attempted to circulate without success. Pulled tubing to 2400', spotted 30 sacks cement. Pulled tubing and waited on cement. Ran in hole and tagged cement at 2131'. Attempted to circulate without success. Pulled tubing to 1000', spotted 35 sacks cement. Pulled tubing and waited on cement. Ran in hole did not tag plug. Ran tubing to 1000' and spotted 35 sacks cement. Pulled tubing.			
8-27-75 Tagged cement at 1100'. Ran tubing to 1000' and established circulation. Pumped 35 sacks cement. Pull out of hole with tubing. Perforated 5 1/2" casing at 344'. Established circulation. Pumped 90 sacks cement circulating to surface via 8 5/8" x 5 1/2" annulus leaving 5 1/2" full to surface.			
9-11-75	Installed 4' marker. Backfilled pit. Cleaned up of Surface Restoration Intention" filed 6-30-75.	location as per "Statement	
18. I hereby certi	the bat the love going is true and correct TITLE Senior Drilling Eng	September 22, 197	
(This space f	J. W. Leonard for Federal or State office use)	Oy ····································	
APPROVED BY TITLE 1975 DATE			
	*See Instructions on Reverse Side DISTR	R R. BAUWN	
	See instructions on Reverse Side Dist	-	