

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HUBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION

MAY 31 8 12 AM '68

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
876

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Ryder Tract Management Company	8. Farm or Lease Name Taylor
3. Address of Operator 922 - 8th Street, Wichita Falls, Texas 76301	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>600</u> FEET FROM THE <u>1</u> <u>ST</u> LINE, SECTION <u>10</u> TOWNSHIP <u>17</u> RANGE <u>12</u> N.M.P.M.	10. Field and Pool, or Wildcat Paljamar
15. Elevation (Show whether DF, RT, GR, etc.) 4158 DF	12. County Dea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-25-68 Pulled 1656' casing.
Set cast iron bridge plug at 3840', capped w/1 sack (7') cement.
Set 25 sx cmt. at casing stub @ 1645'.
Set 25 sx cmt. at base of surface pipe.
Set 10 sx cmt. at top of surface.
Set metal marker at well site.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joann Halsey TITLE Agent DATE May 27, 1968
APPROVED BY John W. Ryan TITLE Agent DATE May 27, 1968
CONDITIONS OF APPROVAL, IF ANY: