

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

HOBBBS OFFICE O. C. C.  
NEW MEXICO OIL CONSERVATION COMMISSION

MAY 31 8 13 AM '68

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Rylos Holt Management Company	8. Farm or Lease Name Cockburn Grinble
3. Address of Operator 922 - 8th Street, Wichita Falls, Texas 76301	9. Well No. 1
4. Location of Well UNIT LETTER _____, _____ FEET FROM THE _____ North _____ LINE AND _____ FEET FROM THE _____ LINE, SECTION _____, TOWNSHIP _____, RANGE _____, NMPM.	10. Field and Pool, or Wildcat Voljaer
15. Elevation (Show whether DF, RT, GR, etc.) no record	12. County Tos

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-1-66 Pull 984' casing.

Set cast iron bridge plug @ 3151' capped w/ 1 inch cement.

Set 30 sx cnt. at casing stub @ 990'.

Set 10 sx cnt. in top of surface.

Set metal marker at well site.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Joann Halsey</u>	TITLE <u>Agent</u>	DATE <u>May 29, 1968</u>
APPROVED BY <u>John W. Runyon</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		