

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-2229	
7. Unit Agreement Name	
8. Farm or Lease Name	
State 13	
9. Well No.	
5	
10. Field and Pool, or Wildcat	
Maljamar (G-SA)	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator	
Murphy H. Baxter	
3. Address of Operator	
P. O. Box 2040, Midland, Texas 79701	
4. Location of Well	
UNIT LETTER <u>10</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM	
THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>17-S</u> RANGE <u>33-E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
4090 GL 4099 DF	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Estimated Starting Date 8/16/78.

1. Run 4 3/4" bit to 4340' In 5 1/2" csg.
2. Run cement retainer and set above lower perforations at 4230'.
3. Squeeze cement perforations 4323 -34'.
4. Acidize perforations 4045-4158'.
5. Put well on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>S. G. Scott</u>	TITLE <u>Engineer</u>	DATE <u>7/28/78</u>
APPROVED BY <u>Jerry Sexton</u>	TITLE <u>Dpt. 1. Supv.</u>	DATE <u>JUL 31 1978</u>
CONDITIONS OF APPROVAL, IF ANY		


RECEIVED

NOV 11 1978

INFORMATION COMM
BUREAU

State 13 Well No. 5
Aljizmar Field
Lea County, N.M.

Well Schematic



RECEIVED

JUL 8 11 1978

OIL CONSERVATION COMM.
HOURS: 9 A.M.