

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Conoco Inc.		8. Farm or Lease Name TAYLOR
3. Address of Operator P. O. Box 460, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>14</u> TOWNSHIP <u>17-S</u> RANGE <u>32-E</u> NMPM.		10. Field and Pool, or Wildcat MALJAMAR G/SA
15. Elevation (Show whether DF, RT, GR, etc.)		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

MIRU. SET PKR @ 3650'. SQUEEZE PERFS 3693'-3814' w/65 sxs cmt. FLUSH w/22 BBLs TFW. WOC. Re-squeeze AS NECESSARY. DO cmt TO 3820'. DO CIBP @ 3825' + OH TO 3946'. LAND WHIPSTOCK IN OH PKR @ 3946'. Pump 8 sxs CLASS "H" cmt 3876'-3946'. WOC. DO cmt @ 3876' + KICK OFF WHIPSTOCK @ 3884'. DRILL A 4 3/4" HOLE TO 4070' TVD w/3° DEVIATION. LOG. COMPLETION PROCEDURE WILL FOLLOW LOG INTERPRETATIONS.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Administrative Supervisor DATE 1/6/84
ORIGINAL SIGNED BY JERRY SEXTON JAN 9 1984

RECEIVED

JAN 9 1984

C.C.D.
HOLDS OFFICE