

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State ☐	Fee ☒
5. State Oil & Gas Lease No.		

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>Injection</u>	7. Unit Agreement Name
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>Att. Taylor</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, NM 88240</u>	9. Well No. <u>No. 3</u>
4. Location of Well UNIT LETTER <u>N</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980'</u> FEET FROM THE <u>West</u> LINE, SECTION <u>14</u> TOWNSHIP <u>17S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat <u>Maljamar G-SA</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Dea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. Set cmt retained at 3905'. Mix and pump 100 sxs class "c" into OH section. Rmpd 8 BW down csq. Well fluid back approximately 100 sxs cmt. Pressure csq to 1500 psi. R1H w/ 5 1/2" tension pkr. Test below pkr from 3730'-3818' w/ pump-in rate 2 BPM at 2000 psi. Set pkr at 3580'. Mix & pmpd 100 sxs class "c" cmt below pkr. Displace w/ 16 BW. Red pkr at 3580'. Rmpd 40 bbls 10" brine gel. Spot 12 sxs class "c" cmt. Plug over interval 2150'-2250'. Perf 4 holes at 970'. Establish Circ down 5 1/2" csq & up 8 7/8" csq to surface. Set 5 1/2" cement retained at 916'. Mix & pump 215 sxs class "c" cmt thru retained w/ good cmt returns out 8 7/8" surface csq. Stung out of retained leaving 50' of cmt on top of retained Circ hole w/ 10" brine gel. Spot 6 sxs of cmt

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. J. Finney DE FINNEY TITLE Administrative Supervisor DATE 6/16/87

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE AUG 13 1987

CONDITIONS OF APPROVAL, IF ANY:
nm 000 - 11.00.121 L.O.

A.C. Taylor No. 3

Pg. 2

over interval 0'-50'. Install P & A marker