

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPI
(Other instructions
verse side)TE*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0315712

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injection well		7. UNIT AGREEMENT NAME Maljamar (Grayburg)	
2. NAME OF OPERATOR Chevron Oil Company		8. FARM OR LEASE NAME Maljamar Unit	
3. ADDRESS OF OPERATOR P. O. Box 1660, Midland, Texas 79701		9. WELL NO. 77	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit H, 2310' FNL, 660' FEL, Sec. 15, T-17-S, R-32-E, NMPM		10. FIELD AND POOL, OR WILDCAT Maljamar (Grayburg-San And)	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) GR 4056	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15, T-17-S, R-32-E, NMPM	
		12. COUNTY OR PARISH Lea	13. STATE New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work to commence before third quarter 1976. Federal office will be notified prior to commencing actual plugging operations.

1. Dig pit and cellar.
2. Run in hole with tubing, open ended, to 3700', displace hole with 9.5 ppg mud laden fluid. Spot 25 sxs cement. Pull tubing to 2400' and spot 30 sxs cement. Pull tubing to 1000' and spot 35 sxs cement. Pull out of hole with tubing.
3. Perforate 5½" casing at 352'. Establish circulation. Pump sufficient cement to circulate to surface via annulus leaving 5½" casing full.
4. Cut off casing 2-3' below ground level. Set 4' marker. Back fill pits and cellar. Clean up location as per Federal or State requirements.

18. I hereby certify that the foregoing is true and correct

SIGNED J. W. LeonardTITLE Drilling SupervisorDATE 3-4-76

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED
AS AMENDED
JUL 26 1976ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

U. S. Geological Survey
P. O. Box 1157
Hobbs, New Mexico

HOBBS DISTRICT

Operator: Chevron Oil Company
Well: No. 77 Maljamar Grayburg Unit
Lease No. New Mexico 0315712

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Hobbs office (telephone (505) 393-3612) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e., ripping of pad and/or access road, reseeding, etc. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
5. If 5½" casing is not pulled from below 1000 feet, perforate 5½" casing at 1000 feet and squeeze with 100 sacks of cement, leaving 200-foot cement plug inside casing in interval 800 to 1000 feet.