

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 20-025-0058200
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-155-5
7. Lease Name or Unit Agreement Name MCA Unit #1
8. Well No. 3
9. Pool name or Wildcat Majors Mesa

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER <u>Injection</u>	
2. Name of Operator <u>Camco Inc</u>	
3. Address of Operator <u>PO Box 460 Hobbs NM 88240</u>	
4. Well Location Unit Letter <u>D</u> : <u>460</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>16</u> Township <u>17S</u> Range <u>32E</u> NMPM <u>h2A</u> County _____	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4053' DF</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: _____ ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: _____ ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/27/89 Notified CCD before RU. h2A down packer, pick up 7" cement retainer & run in hole to 3500' set. Pull out of retainer & load hole w/brine gel mud. String into retainer, get injection rate at $1\frac{1}{2}$ bbl per m. Squeeze 105 sks of cem. below retainer. Spotted 25 sks. cement on top retainer. Run in hole to 930' port with 4 shots. R down, est. circ. to surface between 7" & 8 $\frac{5}{8}$ csg. Squeeze 255 sks cement between 7" & 8 $\frac{5}{8}$ csg, circ. cement to surface. Rig down unit. Erect P-A marker. Restore location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. W. Baker TITLE Administrative Supervisor DATE 1/25/90

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY R. A. Seidman TITLE _____ DATE FEB 20 1990

CONDITIONS OF APPROVAL, IF ANY:

OIL & GAS INSPECTOR