

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instruction
reverse side)

Revised Bureau No. 1-100-1
Revised August 31, 1968
LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Injection	7. UNIT AGREEMENT NAME MCA Unit
2. NAME OF OPERATOR Coraco Inc	8. FARM OR LEASE NAME MCA Unit Sty 1
3. ADDRESS OF OPERATOR PO Box 460 Hobbs NM 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit B 690/N + 1980/E	10. FIELD AND POOL, OR WILDCAT Malpais H-SH
14. PERMIT NO. 30-025-0058700	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA S-17 T17S R32E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH MCA
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11/17/89 Notified BLM before RU.
Pump into formation at 1 1/2 bbl perm, rig down off. Pull out of hole with tubing w/off/on tool at 115 ft of 2 3/8 Htg. PU 5 1/2 cmt. Retainer, run in hole w 2 3/8 tubing to 3471. Pull out, load hole w/brine gel mud, sting into retainer squeeze 75 sts cmt. below retainer, spot 25 sts cmt. Run 7 ft of 2 3/8 tub. in hole to 217' circulate cmt. to surf. with 25 st. cmt. lay down tubing, rig down unit w PA equip, set up PA marker - Restore location.

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED W. W. Baker WUB

TITLE Administrative Supervisor

DATE 1/25/90

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 2-24-90

*See Instructions on Reverse Side

RECEIVED

MAR 2 1990

**OCD
HOBBS OFFICE**