

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-0058700
5. Indicate Type of Lease <u>Federal</u> STATE ☐ FEE ☐
6. State Oil & Gas Lease No. HC-0294053
7. Lease Name or Unit Agreement Name MCA Unit Sty 1
8. Well No. 1
9. Pool name or Wildcat Maljamar 21-50

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER <u>Injection</u>	
2. Name of Operator <u>Corcos Inc</u>	
3. Address of Operator <u>PO Box 4100 Hobbs NM 88240</u>	
4. Well Location Unit Letter <u>B</u> : <u>690</u> Feet From The <u>N 44°</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>17</u> Township <u>17 S</u> Range <u>32 E</u> NMPM <u>NEA</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notified OCD before RU.
11/17/89 Pump into formation at 1 1/4 bbl perm, rig down off. Pull out of hole with tubing w/ off/on tool at 11 fts of 2 3/8 tubg. PL 5 1/2 cmt. retainer, run in hole w 2 3/8 tubing to 3471'. Pull out, load hole w/ brine gel mud, sting into retainer, squeeze 75 sts cmt. below retainer, spot 25 sts cmt. Run 7 fts of 2 3/8 tub in hole to 217' circ cmt. to surf with 25 sl cmt. down tubing, rig down with P-A rigup, set up P-A marker. Restore location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W W Baker W W Baker TITLE Administrative Supervisor DATE 1/25/90

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

FOR RECORD ONLY

APPROVED BY _____ TITLE _____ DATE FEB 02 1990

CONDITIONS OF APPROVAL, IF ANY:

R A W

c