

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions
reverse side)

Form Approved
Budget Bureau No. 1004-01
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-0603290
2. NAME OF OPERATOR Conoco Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Bx 460 - Hobbs, NM 88240		7. UNIT AGREEMENT NAME MCA Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter A		8. FARM OR LEASE NAME MCA Unit <i>Atty!</i>
14. PERMIT NO. 30-025-0060000		9. WELL NO. No. 2
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		10. FIELD AND POOL, OR WILDCAT Maljamar G-SA
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T17S, R32E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU, ND wellhead and NU BOP.
2. Circ. Well and pull Baker lockset bridge plug w/K-valve @ 3450'. Latch RBP @ 3450'. Equalize pressure through K-valve. Release RBP and POOH.
3. Abandon open hole from 3561-4052'. Set cement retainer at 3500'. Pump 140 sx of cement through retainer. Sting out and dump 25 sx on top of retainer from 3500-3375'. Displace cement. Circ. hole w/drilling mud.
4. Perf. prod. casing @ 920'. Cement surface casing x production casing annulus from 0-920'.
5. Cement surface casing annulus.
6. Cut casing strings 3' below ground level. Erect permanent abandonment marker.

For further technical information contact Henry David at 397-5894.

18. I hereby certify that the foregoing is true and correct

SIGNED W.W. Baker W.W. Baker TITLE Administrative Supervisor DATE July 22, 1989

(This space for Federal or State office use)

APPROVED BY Shammy Shan FOR: SHR DATE 8-15-89
CONDITIONS OF APPROVAL, IF ANY

*See Instructions on Reverse Side