

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other Instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R-1111

5. LEASE DESIGNATION AND SERIAL NO.

LC-029509 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

Box 460, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)At surface
1980' FNL + 1980' FEL of Sec. 21, T-175, R-32E,
in Lea County New Mexico.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

4056' DF

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA Unit

9. WELL NO.

43

10. FIELD AND POOL, OR WILDCAT

Maljamar Field
(G-SA) Pool11. SEC., T., R., M., OR PLK. AND
SURVEY OR AREA

Sec. 21, T-175, R-32E

12. COUNTY OR PARISH 13. STATE

Lea

N. Mex.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*It is proposed to free this well by the following
procedures.

Go in hole w/6 1/4" bit and check tight spot at 1900'.
Clean out till to PB depth of 4108'. Load shot hole w/explosive
5 3/4" cans from 4108' to 4030'. Load hole with blank cans (filled
w/sand) from 4030' to 3950'. Load shot hole w/explosive cans
from 3950' to 3740'. Dump pea gravel and fill to 3650'.
Spot Calseal from 3650' to 3540' w/dump bailer. After
shot drill out pea gravel and Calseal plug to top of
shot at 3740'. Clean out into shot 10'. Place on
Production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert Gault

TITLE

Administrative Section Chief

DATE

7-2-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

USGS-5

*See Instructions on Reverse Side

APPROVED

JUL 3 1969
ARTHUR R. BROWN
DISTRICT ENGINEER