

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN THE
(Other Instructions)
NEW MEXICO 88240

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <u>MCA Unit</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	8. FARM OR LEASE NAME <u>MCA Unit Bty 2</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. WELL NO. <u>91</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>660' FSL & 1980' FEL - Unit Letter O</u>	10. FIELD AND POOL, OR WILDCAT <u>Maljamar G-SA</u>
14. PERMIT NO. <u>30-025-00617</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>21-17S-32E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PCLL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Tag CIBP at 3500' & drill out. Circ hole clean. GIH w/7" 20" cmt retained on 2 1/8" WS to 3491'. Squeeze below retained w/ 280 sxs class "H" w/ 2% CaCl₂. Displace w/ 12 bbls FW. SI. POOH. Reverse out 6 bbls cmt. Spot 58 bbls 9.5 #/gal mud from 3430' - 1900'. Spot 18 sxs class "C" plug from 1900' - 2000'. Spot 40 bbls 9.5 #/gal mud from 1900' - 1000'. Spot 24 sxs class "C" plug from 860' - 1000'. PU to 600'. Circ hole clean. POOH. GIH. Tag cement plug at 874'. POOH. RU. Ref 4' spF at 600'. POOH. RD. RU Dowell establish pumpin rate, 1.5 BPM at 20". Circ to surface. Rmpd 175 sxs class "C" close surface valve. Squeeze to 100" RD. Install P&A marker on 4/17/89.

18. I hereby certify that the foregoing is true and correct

SIGNED William W. Baker
William W. Baker

TITLE Administrative Supervisor

DATE April 26, 1989

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

FOR: CHIEF, MOUNTAIN
TITLE TRAIL, NM

DATE 5-3-89

*See Instructions on Reverse Side