

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other Instructions on reverse side)

Bureau No. 42-11121

5. LEASE DESIGNATION AND SERIAL NO.

LC - 029509 (2)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA UNIT Blyr

9. WELL NO.

30

10. FIELD AND POOL, OR WILDCAT

MHLJ. G-SA REPRESS

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC 22, T-17S, R-32E

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 460, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

660' FWL + 660' FWL of SEC. 22

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3998' DF

12. COUNTY OR PARISH

LEA

13. STATE

N. MEX.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to plug + abandon this well by the following procedure.

Run 2 7/8" tbg w/ overshot and tie into stuck tbg at 2242'. Run tbg cutter and cut tbg at approx 4000'. Squeeze OH w/ 150 sacks of class C cement. Release overshot + pull tbg. Go in hole w/ tbg, packer and retainer. Set retainer at 2000' and squeeze collapsed casing w/ 300 sacks cement. Spot 10 sacks plug at surface and squeeze cement between 10 1/2" + 7" casing. Cap well w/ dry hole marker + restore location

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE 11-12-71

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL

USGS (5) File

MCA Phe

Place additional 25 sack plug in interval 500-900 feet. Hole to be filled with mud between plugs.

*See Instructions on Reverse Side

APPROVED
AS AMENDED
NOV 16 1971
ARTHUR R. BROWN
DISTRICT ENGINEER