MRR#	90043
DIST.	

MAINTENANCE & REMEDIAL REQUEST

LEASE NAME <u>Baish B</u>	WELL	NO. 1	CONOCO	W.I	100%		
OBJECTIVE OF WORK Plug and abandon							
LOCATION 660' FNL & 1650' FWL, Unit C, S	ec. 22. T	17S, R32E C	OUNTY Lea	STATE	NM		
	LD Baish	-Maljamar-Pea			-4-90		
DIVISION_HobbsFIE		The June 1 ou					
WELL CLASSIFICATION WELL STATUS	TD	13,657'	MEASUR	ING POI	NT		
	PBTD	12,190'	20			ABOVE	
	_	9,495'		GL	-7 ''i	LF	
() GAS () SERVICE (X) SHUT-IN	TOC	9,493	(^ /	uL			
	.						
SURFACE & PRODUCTION CASING	LINER			TUBING		PACKER	
SZ GR WT SET@ SXCMT	CEM. ()YES (X)NO		SET @	TYPE	SET @	
13-3/8" <u>H-40 480 473 350</u>	_ TOP E	STM SIZE WT	·		<u></u>	<u>8885′</u>	
<u>9-5/8" J-55 36&40 4734 3109</u>							
7" N-80 26-35 12,500 800							
FORMATION PERF/OH TOP BTM	NEP	FORMATION	PERF/OH	TOP	BTM	NEP	
Abo <u>Perf 8928' 8964'</u>			•				
<u>Wolfcamp Perf 9808' 9875'</u>	:						
MISC. DATA (COLLAPSED CASING, BRIDGE PLUG	ETC)	PROBLEM		RECUR	RING		
MISC. DATA (CULLAPSED CASING, BRIDGE FLOG	, LIC.)		EHAVIOR		YES		
		() MECHAN		-	NO		
RBP @ 8885'			IICAL	ι <i>γ</i>	no		
		TED INCOLASE		TIMATER	PAYOUT		
ALLOWABLE PRESENT PROD.	EXPE	CTED INCREASE	_				
DATE BOPD		BOPD		ERIOD :_			
BOPD MCFD		MCFD		PRICE:_			
MCFD BWPD		BWPD	GAS	PRICE:_			

JUSTIFICATION

Funds of \$23,300 are requested to permanently plug and abandon Baish B No. 1.

This well was originally drilled as a Devonian test in 1960. However unsuccessful drill stem tests in the Devonian resulted in a Maljamar Strawn completion . This formation produced 36 MBO from 1960 to 1962 when it was shut in as depleted. The well was then recompleted to the Baish Wolfcamp zone. In 1963 the Maljamar Abo zone was also opened, and the well was dually completed. The well was downhole commingled in 1970 between the Abo and Wolfcamp formations, and at this time the 7" production casing was found to be parted at \pm 2228'. The free upper section of casing was removed. From 1970 until June of 1988, both zones produced and were occasionally acidized to remove scale and stimulate production. In July of 1988 the well was temporarily abandoned due to marginally economic production rates and mechanical problems with the pumping equipment. Cumulative production from the Baish Wolfcamp zone was 164 MBO and 0.3 BCF while the Maljamar Abo zone has produced 144 MBO and 0.3 BCF.

A recent casing integrity test run on this well indicates a severe casing leak has developed in either the 7" or 9-5/8" casing string. An evaluation of this well does not indicate any further potential to economically restore production in any of the previous zones. The mechanical integrity of the casing left in this well also eliminates a risky uphole recompletion attempt in either the Paddock or Grayburg-San Andres zones. (These zones may be tested in offset producers that have mechanically sound casing).

Therefore, based on the depleted status of the formerly produced zones, and the very poor uphole casing integrity, it is recommended to permanently plug and abandon the Baish B No. 1.

ESTIMATED GROSS COST: \$23,300 APPROVED: STB:dw And Alton BAISHB#1.MRR Bruth. Meyer PREPARED BY: STB ESTIMATED NET COST: \$23,300 CHARGE: Abandonment DATE: DIST: MRR: 90043 5/25/40 020cr '90