Form 3160-5 (June 1990 🛫 🗐

1. Type of We

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## N.P. DILCONS. COMMISSION P.C. \_OX\_1980 OVER HOBBS NEW MEXICO 88240

Expires: March 31 1993

5 Lease Designation and Serial No

7 If Unit or CA Agreement Designation

LC 058698B 6 If Indian Allottee or Tripe Name

## SUNDRY NOTICES AND REPORTS ON WELLS

Do notibe this form for proposals to drill or to deepen or reentry to a different reservoir Lise "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

8 Well Name and No

MCA UNIT WELL # 33

9 API Well No.

30-025-00655 10 Field and Pool or Exploratory Area

MALJAMAR GRAYBURG SAN ANDRES 11 County or Parish, State

LEA, NM

X Oi Weil	Gas Well	INJECTION Other				
Name of Opera		Othe				
CONOCOII						
Address and Te						_
10 DESTA Location of Well	DR STE 100 (Footage Sec. 1	W, MIDLAND, TX. T. R. M. or Survey Des	79705 cription)	(915) (915)	684 - 685 - :	638 542
SURFACE: TD:	1980' FNL & Same	1965' FEL of Section	on <b>2</b> 7, T-	17S, F	₹-32E	

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUPRISSION

TIPE OF SUBMISSION	TYPE OF ACTIO	ON
Notice of Intent	X Abandonment P&A	Change of Plans
Subsequent Report	Recompletion	New Construction
	Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well)
oposed or Completed Operations /Clearly state all postioner details		Completion or Recompletion Report and Log form )

- ions (Clearly state all pertinent details, and give perinent dates, including estimated date of starting any proposed work. If well is directionally drived give subsurface locations and measured and true vertical depths for a limarkers and zones pertinent to this work.)
  - 10-16-95 Move in, hold safety meeting, rig up, put on BOP, pull tubing out of hole, run in hole with 7" CIBP. Set at 1950, Circulate mud, test casing to 1000#, spot 10 sx cement on top of CIBP from 1950' - 1890', pull tubing, perforate well at 1175' w/ 4jspf., could not pump into well at 1000#, spot 25 sx plug from 1228' - 1078'. Perforate well at 200', good circulation to surface in 8 5/8" casing, shut down.
  - 10-17-95. Circulate 40 sx cement down 7" casing to 200" up 5.5/8" to surface, cut off we'lhead, put in marker, rig down. clean location, move off.

Class "C" cement - Mud between plugs - 25# Salt gel/bt1.

Cement retainer - 3450' - 35' cement

RBP - 2200' - 10' sand

CIBP - 1950' - 60' cement

25 sx cement 1228' - 1078'

40 sx cement 200' - surface.

Country as to place the convertible amety under bond is retained until

sulfice restoration is completed

State office use

Ann E. Riisnie REGULATORY AGENT Title

r een 102 û bewij Approved by Conditions of approval if any

Title

