

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Conoco, Inc.

3. Address and Telephone No.
10 Desta Dr. Ste 100W, Midland, TX 79705

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980' FNL & 1965' FEL
Sec. 23, T-17S, R-32E

5. Lease Designation and Serial No.
LC 058698B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
MCA Unit No. 33

9. API Well No.
30-025-00655

10. Field and Pool, or Exploratory Area
Pearsall Queen

11. County or Parish, State
Lea

12 CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to recomplate this well from the Grayburg-San Andres to the Queen by the following procedure:

1. Run CBL in 7" casing from retainer @ 3458' to the TOC.
2. Squeeze with 140 sxs class C cement w/2% CaCl.
3. Isolate casing leak between 1180'-2140' and squeeze with 50 sxs cement.
4. Perforate Queen from 3304'-3330' with 52 holes (2 jsp).
5. Acidize perfs with 35 bbls of 15% HCl and frac.
6. Put on production.

NOTE: Since the Queen formation is outside the MCA unitized interval, this well will be renamed to the Miller B #6 if the recompletion is successful. This name change will be filed with the completion and C-104 reports.

14. I hereby certify that the foregoing is true and correct

Signed [Signature]
(This space for Federal or State office use)

Title Sr. Conservation Coordinator

Date 11/22/94

Approved by JOE G. LARA
Conditions of approval, if any:

Title REGIONAL ENGINEER

Date 12/14/94