

UNIT STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLIC
(Other instructions on
reverse side)Form approved,
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 058698(2)

6. IF INDIAN, ALLOTTEE, OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA UNIT

9. WELL NO.

76

10. FIELD AND POOL, OR WILDCAT

MALT G-SA REPRESS

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 23, T-17S, R-32E

12. COUNTY OR PARISH

LEA

13. STATE

N.M.

OIL WELL ☐ GAS WELL ☐ OTHER

WATER INJECTION

2. NAME OF OPERATOR

CONTINENTAL OIL COMPANY

3. ADDRESS OF OPERATOR

Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FSL & 660' FWL OF SEC. 23

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☒MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

INSTALL CSG.

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent
to this work.)*

To prevent loss of water to non-pay intervals, the following work is proposed: Run csq. insp. log to determine if 4 1/2" csq. should be run as full string or if 400' liner should be set. Plug back in OH w/ pea gravel and sand to 3840'. Run 4 1/2" 9.5# K-55 csq. either as full string or liner of 400' depending on log. If full string, cmt w/ 325 sks. Class "C" cmt. If liner, cmt w/ 65 sks. Class "C". Drill out cmt & test to 1500#. Clean out to TD 4120'. Place back on injection.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Sr. ANALYST

DATE

10-25-74

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

1974

USGS-5, MCA-3, File

*See Instructions on Reverse Side