

COPY TO O. C. C.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TWO PARTS
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC-059152 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Johns "B" DE

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Maljamar

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

24-17S-32E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER P&A2. NAME OF OPERATOR **ARCO Oil and Gas Company**
Division of Atlantic Richfield Company

3. ADDRESS OF OPERATOR

Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FNL & 660' FWL (Unit letter E)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4049' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐Plug & Abandon ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

RU 7/17/79. POH w/rods, inst BOP. Swbd well down. POH w/tbg & pump. Set cmt retr @ 3533'. Pmpd 100 sx cmt, squeezed w/2000#. RO 4 bbls cmt. RIH w/RTTS pkr, tagged cmt plug @ 3300', set pkr @ 2716'. Pressure tested plug to 700# 30 mins OK. POH w/pkr. RIH w/tbg OE, spot cmt plug 2716-2316'. Perforated w/4 JS @ 1050'. RIH w/pkr, established circ. POH w/pkr. RIH w/cmt retr, set @ 912'. Pmpd 225 sx cmt to surf. Closed BH valve, had 300# on surf. Swaged 7" csg, pmpd 300 gals 15% acid. Pmpd 200 sx Cl H cmt w/2% CaCl @ 1200#. SIP 600#. Pressure tested 10-3/4" x 7" csg to 600# for 30 mins OK. Installed dry hole marker. Well P&A eff 7/26/79.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Dist. Drlg. Supt.

DATE

8/1/79

APPROVED

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side