Form 9-331 (May 1963)	UNFED STATES DEPARTMEN OF THE INTER	SUBMIT IN TRIPLY	5. LEASE DESIGNATION	a <u>No. 42-R1424</u> . AND SERIAL NO.	
	GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS this form for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT—" for such	back to a different reservoir.	LC 059152 6. IF INDIAN, ALLOTTEE		
1. OIL S GAS OTHER			7. UNIT AGREEMENT NAM	7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR			1	S. FARM OR LEASE NAME	
Atlantic Richfield Company 3. ADDRESS OF OPERATOR				Johns "B" DE	
P. O. Box 1710, Hobbs, New Mexico 88240			3		
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 			10. FIELD AND POOL, OR WILDCAT		
			Maljamar Grayburg 11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA		
1980' FSL	& 1980' FWL (Unit letter K)	~	24-17S-32E		
14. PERMIT NO.	15. ELEVATIONS (Show whether r)F, RT, GR, etc.)	12. COUNTY OB PARISH	13. STATE	
	4070' DF		Lea	N.M.	
16.	Check Appropriate Box To Indicate	Nature of Notice, Report, o	r Other Data	,	
	NOTICE OF INTENTION TO:	SUBS	SEQUENT REPORT OF:		
TEST WATER S	HUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	ELL	
FRACTURE TREA		FRACTURE TREATMENT	ALTERING CA		
SHOOT OR ACID REPAIR WELL	IZE ABANDON*	SHOOTING OR ACIDIZING (Other)	ABANDONMEN		
(Other)	Plug & Abandon	(NOTE : Report rest	ults of multiple completion of multiple completion for the second s	m.)	
17. DESCRIBE PROPO proposed wor nent to this v	SED OR COMPLETED OPERATIONS (Clearly state all pertinerk. If well is directionally drilled, give subsurface loc work.)*	nt details, and give pertinent da ations and measured and true ver	tes, including estimated data rtical depths for all markers	of starting any and zones perti-	
TD 4345'. 8-5/8" OD 5 [‡] " OD 14# DV tool @ 1. RU, kil if nece 2. RIH w/5 3. Cement 4. Spot 20 5. Spot 20 6. Perfora 7. Swage t perfs @ 8. Install Note: Hol	P&A in the following manner: Completed OH 3840-4345'. 28 = csg set @ 129' & cmtd w/40 s csg set @ 3840' & cmtd w/100 sx 1133' & cmtd w/250 sx. 1 well, install BOP & POH w/comp ssary. ¹ " cmt retr, set retr @ approx 3 thru retr w/200 sx Cl C cont'g 4 9 sx Cl C cmt cont'g 4% gel (100' 1 sx Cl C cmt cont'g 4% gel (100' 1 te 5 ¹ " OD csg w/4 JS @ 200'. op of 5 ¹ ¹ " csg & displace 100 sx 200' & circ 8-5/8" X 5 ¹ ¹ " annulu regulation dry hole marker, cle e will be filled with heavy gell	. TOC unknown. detion assy. GIH w/ 760'. % gel. minimum plug) @ 276 minimum plug) @ 176 Cl C cmt cont'g 4% g to surface. an & level location	60' inside 5 ¹ " cs 60' inside 5 ¹ " cs gel & 6# salt/sk	g .	
SIGNED	TITLE I	Dist. Drlg. Supv.	DATE	/76	
(This space for	r Federal or State office use)	· · · · · · · · · · · · · · · · · · ·	TTED_1		
APPROVED BY CONDITIONS	Y TITLE OF APPROVAL, IF ANY:		NDED /		
		N	201978 ANN		
	*See Instructio	ns on Reverse Side	BROWN		
		ARTH	AUR R. BROWN		