

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NEW MEXICO

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
Conoco Inc.
3. ADDRESS OF OPERATOR
P.O. Box 460 - Hobbs, New Mexico 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
660' FNL & 660' FEL - Unit Letter A
14. PERMIT NO.
30-025-00684
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
16. RECEIVED
NOV 16 10 59 AM '88
7. UNIT AGREEMENT NAME
MCA Unit
8. FARM OR LEASE NAME
MCA Unit Bty 4
9. WELL NO.
132
10. FIELD AND POOL, OR WILDCAT
Maliama C-SA
11. SEC., T.R., M., OR BLK. AND
SURVEY OR AREA
25-17S-32E
12. COUNTY OR PARISH 13. STATE
Lea NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Mill out tight spots at 50' & 1650'. Clean out to 3475'. Set cement retainer at 3411'. Rmpd 225 sxs class "C" below retainer, left 1 bbl on top. Spot salt gel to 2400'. Spot 25 sxs cement plug from 2400'-2160'. Set cement retainer at 1205'. Rmpd 250 sxs "C" w/13#/sx salt & 4% bentonite. Followed w/250 sxs "C" w/10# Cal-Seal/sx & 6.5#/sx salt. Spot cement from 1205' to surface. POOH. Squeeze down csq w/65 sxs, circ cement up 5 1/2" x 8 1/4" annulus. Closed csq valves & squeeze thru dirt. Rig down. Cut off csq, install P&A marker on 10/7/88

I hereby certify that the foregoing is true and correct.

SIGNED: *[Signature]* D. F. DWYER

TITLE: Administrative Supervisor

DATE: November 14, 1988

APPROVED BY STATE AGENCY:

APPROVED BY BUREAU OF LAND MANAGEMENT:

TITLE:

DATE: 1-4-89

APPROVED BY FIELD OFFICE:

APPROVED BY SURFACE DISTRICT:

*See instructions on Reverse Side