

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TYPE
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-058697B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

MCA Unit

8. FARM OR LEASE NAME

MCA Unit Bldg 4

9. WELL NO.

132

10. FIELD AND POOL, OR WILDCAT

Maljamar G-SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

25-17S-32E

12. COUNTY OR PARISH

Lea

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Conoco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 460 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FNL & 660' FEL - Unit Letter A

14. PERMIT NO.

30-025-00684

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRR. If well dead, perf nipple on workstring to below 3900'. Spot cement from TD to 3400'. Maximum cement 110 sks of class "C". If flowing set retainer at 3400'. Pump 225 sks class "C". String out of retainer & spot 1 bbl on top.
2. Spot mud from 3340'-2400'. Spot 25 sks class "C" from 2400'-2160'.
3. Set retainer at 1200'. Pump 250 sks class "C" w/13#/sk salt & 4% bentonite. Follow w/250 sks class "C" w/10# Cal-Seal & 6.5#/sk salt. String out of retainer & spot 1 bbl cement on top. Circ clear.
4. If surface flow shut-off. Run to 100'. Circ cement to surface (9 sks class "C"). Squeeze w/50 sks class "C" cut off csq & install PTA marker. If surface flow is not shut off, shoot squeeze at 1100' w/4 jspf. Set retainer, pump 500 sks class "C", string out of retainer, spot 1 bbl cement on top & circulate mud to surface.

18. I hereby certify that the foregoing is true and correct

SIGNED Rex C. Finner

for D. Finner
TITLE Administrative Supervisor

DATE 7/27/88

FOR SUBMITTER (Federal or State office use)

APPROVAL OF COMMISSIONER OF LAND

COMMISSIONER OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED
7-28-88
11 35 AM '88

*See Instructions on Reverse Side

Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad(6) OXY(1) FPCO(1) File