

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
verse side)

NE
re

Form approved
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Las Cruces 058697B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Continental Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

**1980' FNL and 660' FEL, Section 25, T-17S, R-32E,
Lea County, New Mexico N.M.P.M.**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4024 DF

7. UNIT AGREEMENT NAME

M.C.A. Unit

8. FARM OR LEASE NAME

M.C.A.

9. WELL NO.

137

10. FIELD AND POOL, OR WILDCAT

Maljamar

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 25, T-17S, R-32E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) **Cleanout**

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The well presently has the tubing stuck in the hole as evident by pulling job done on 6-15-63. On latest test, dated 8-4-66, well pumped 28 BOPD, 2 BW, with a G.O.R. of 321.1.

It is proposed to cleanout this well using the following procedure:

1. Pull rods and tubing
2. Run free point indicator
3. Cut off tubing, if necessary, and washover to recover
4. Cleanout to 4220'
5. Rerun rods and tubing
6. Place well back on production

A subsequent report will be submitted upon completion of this work.

18. I hereby certify that the foregoing is true and correct

SIGNED **Paul M. Stephens**

TITLE **Staff Supervisor**

DATE **10-25-66**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

USGS (5), File

APPROVED
OCT 27 1966
A. H. GILLES
DISTRICT ENGINEER

