

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <i>MCA Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA Unit Bty 4</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. WELL NO. <i>128</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>1345' FNL & 1345' FWL - Unit Letter F</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljamar G-SA</i>
14. PERMIT NO. <i>30-025-00694</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>25-17S-32E</i>
15. ELEVATIONS (Show whether DF, RT, CR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) <i>Deepen</i>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Hot oil thq. Tag at 4140'. Pump 3.5 BPM w/.5 BPM returns. Pump 12 sxs oyster shells & 160 BW. Jet wash & CO shot section from 4000'-4075'. Circulate clean. Pump 6 sxs oyster shells. Est circ. CO & jet wash to 4140'. CO & jet wash from 4000'-4150'. Circ clean. CO & jet wash from 4140'-4160'. Document from 4160'-4191'. POOH. Tag at 4191'. Drill new formation 4191'-4237'. POOH. Tag at 4237'. Drill new formation from 4237'-4280'. POOH. Tag at 4280'. Drill new formation from 4280'-4310'. POOH. Tag at 4310'. Drill new formation 4310'-4330'. Circulate clean. POOH. Run G-R-CNL from 4330'-3800'. Acidize OH w/150 bbls 10% HCL-NE-FE.

19. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* *W. FINNEY*

TITLE *Administrative Supervisor*

DATE *June 27, 1988*

Place space for Federal or State office use

APPROVAL OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

SJS

CARLESON, NEW MEXICO

It is a crime for any person knowingly and willfully to make to any department or agency of the Department of the Interior, or to any officer or employee thereof, any false or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carleson (6) OXU (1) E PPH (1) 4-11