

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN T
(Other Instruc
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <i>MCA Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA Unit</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. WELL NO. <i>128</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>1345' FNL & 1345' FWL - Unit Letter F</i>	10. FIELD AND POOL, OR WILDCAT <i>Maliama G-SA</i>
14. PERMIT NO. <i>30-025-00694</i>	11. SEC. T. E. M. OR BLK. AND SURVEY OR AREA <i>25-175-32E</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <i>Dea</i>
	13. STATE <i>NM</i>

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☒
(Other) <i>Deepen</i>			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRR
2. Clean out & jet wash to PBTD at 4150'.
3. Deepen from 4150'-4330'.
4. Run GR Neutron log from 4330'-3800'.
5. Spot 2940 gals acid over open hole interval 4012'-4330'.
Let soak 2 hrs, agitating every 30 minutes w/workstring.
6. Run pump-in tracer survey. If 7th zone (4150'-4330') is taking 10% of fluid or more, set pkr at 3800' & acidize open hole interval w/4200 gals in 5 stages as per rock salt to divert between stages.
7. Run production equipment.

18. I hereby certify that the foregoing is true and correct

SIGNED *Administrative Supervisor*

TITLE *Administrative Supervisor*

DATE *January 29, 1988*

(This space for Federal or State office use)

APPROVAL OF
COMMISSIONERS OF APPROVAL, IF ANY:

TITLE

DATE *2-5-88*

*See instructions on Reverse Side

Under 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

B.M. Carlsbad (6) Hondo (2) Cities (1) FPCO (1) File