

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. OIL CONS. COMMISSION
P.O. BOX 1980
TORRES, NEW MEXICO 88240

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other

INJECTION

2. Name of Operator
CONOCO INC.

3. Address and Telephone No.
10 Desta Drive STE 100W, Midland, TX 79705 (915) 686-6551

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL, 1980' FWL
SEC. 27, T-17S, R-32E, UNIT LTR 'F'

7. If Unit or CA, Agreement Designation

8. Well Name and No.

MCA #147

9. API Well No.

30-025-00719

10. Field and Pool, or Exploratory Area

MAIJAMAR GRAYBURG SAN ANDR

11. County or Parish, State

LEA, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☒ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9-7-94 MIRU. RELEASED ON/OFF TOOL & CIRC 90 BBLs 10# BRINE. POOH W/TBG & PKR. RBIH W/ KILL STRING. POOH W/TBG. RIH W 10 STANDS % & SV. TESTED TO 2000#. GOOD. POOH. RIH W/PKR. SET PKR. TRY TO LOAD & TEST CSG. WOULDN'T LOAD. MOVED PKR UP 30'. COULDN'T LOAD. PKR @ 3700'. RELEASED ON/OFF TOOL. POOH W/TBG. RIH W/ 4" LOC-SET SET PKR @ 3670'. COULDN'T GET TEST ONSCG ABOVE PKR. MOVED PKR UP. TEST CSG. GOT A GOOD TEST @ 3520 TO SURF 500# NO LEAKS. RELEASED & MOVED PKR TO 3000'. POOH W/PKR & TBG. RIH W/ON OFF TOOL. LATCHED ON TO INTERLOCK. RELEASED & POOH. RIH W/SCRAPPER & 64 JUS 2 3/8 WS. CIRC BRINE RIH SCRAPPER TO 3820'. WELL CAME IN. CIRC 250 BBLs 10# BRINE. POOH W/SCRAPPER. RIH W/ CIBP & SET @ 3800'. POOH W/TBG & RAN 2 JTS OF TAILPIPE ON 5 1/2 FULLBORE. SET PKR @ 3325 WQZ WELL W/188SX CMT. RELEASED PKR. POOH W/TBG. RIH 8-2 3/8 DC, 3 1/8 BIT & TAGGED @ 3384. DO CMT TO 3800'. TAGGED CIBP. DISPLACED HOLE W/10# BRINE. POOH W/TBG. LOST CONE OFF BIT. RIH W/KS. POOH W/TBG. RIH W/MILL TO 3800' CIRC. TAG UP @ 3808' CLEANED OUT SCALE & MILLED UP CIBP DOWN TO 4088'. POOH WS. RIH W/OTIS INTERLOCK PKR & INJ IPC TBG. SET PKR. REL ON/OFF TOOL. LATCHD ON TO PKR. LATCHED ON TO PKR. COULDN'T RELEASE OR SHEAR. GOT OF PKR. POOH W/TBG. PICKED UP 6- 2 3/8 DC, BUMPERSUB & 2 3/8 WS. RIH TO TOP OF PKR. LATCHED ON TO PKR. POOH W/PKR. RIH W/ BIT & SCRAPPER TO 3940'. POOH. RIH W/PKR HIT TIGHT SPOT @ 3748. SET PKR @ 3746'. POOH WS. RIH W/INJ TBG. POOH FLUG OUT OF PKR. CHECKED PRESS. 0-ON CSG. 800# ON TBG. HOOKED UP INJ LINE. RD. 10-4-94

14. I hereby certify that the foregoing is true and correct

Signed *[Signature]*

Title STAFF REGULATORY ASSISTANT

Date 11-11-94

(This space for Federal or State office use)

Approved by
Conditions of approval, if any:

Title

ACCEPTED FOR RECORD

[Signature]
DEC 12 1994

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See instruction on Reverse Side

CARLSBAD, NEW MEXICO

RECEIVED

DEC 14 1994
OCD HOBBS
OFFICE