

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NEW MEXICO 88240
RECEIVED

Budget Bureau No. 1004-01
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Injection</u>	2. NAME OF OPERATOR <u>Conoco Inc.</u>	7. UNIT AGREEMENT NAME <u>MCA Unit Bty 3</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, NM 88240</u>	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>Unit # 1980' FSL + 660' FWL</u>	8. FARM OR LEASE NAME
14. PERMIT NO. <u>30-025-00728</u>	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	9. WELL NO. <u>#180</u>
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		10. FIELD AND POOL, OR WILDCAT <u>Maljamas G-SA</u>
NOTICE OF INTENTION TO:		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 27, T17S, R32E</u>
SUBSEQUENT REPORT OF:		12. COUNTY OR PARISH <u>Lea</u>
		13. STATE <u>NM</u>

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) <u>Puddle Pack + Run Lines</u>	
(Other)			
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-19-89 Clean-out & jet wash to 4170'. "Puddle Pack" open hole section as follows: Pump 5 Bbl gel, 50 Bbl sand slurry, 4 Bbl gel + 10.5 Bbl filtered 2% KCL water. Drill out. Pump 200 H₂O. Class "H" cmt w/2% CaCl to sealize leaks. D.O. + Clean out. GIH w/2 7/8" fiberglass liner. BOL @ 4171', TOL @ 3498'. Cmt w/100 H₂O. 50/50 poz Class "C" cmt. Drill out. Perf. w/2 JSF @ 3844-50, 3862-85, 3888-93, 3897-3906, 3910-22, 3928-40, 3968-72, 3978-94, 4022-65, 4075-80. Acidize w/175 Bbl 15% HCL-NE-FE acid. Run production equipment.

18. I hereby certify that the foregoing is true and correct

SIGNED W.W. Baker W.W. Baker TITLE Adm Supervisor DATE 11-27-89

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Adm

*See Instructions on Reverse Side