

UNIT STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Queen B
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. No. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1249' FSL & 2605' FEL - Unit Letter O	10. FIELD AND POOL, OR WILDCAT Pensall Queen
14. PERMIT NO. 30-025-00731	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 27-17S-32E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRU.
2. G1H w/ muleshoe jt on 2 7/8" workstring & tag bottom. Plugback OH w/ sand from TOF to 3300'. POOH. G1H w/ 5 1/2" cement retained & set at 3100'. Pump 75 sxs class "C" cement. Cement below retained w/ 50 sxs. Pullout of retained & spot remaining 25 sxs cement on top of retained. Pull up & circulate well w/ 10 ppq mud.
3. Spot a 25 sxs class "C" cement plug across base of salt section from 2270' - 2030'. Pull up & reverse clean. POOH.
4. G1H w/ 4" csg gun. Perf 2 spf at 1075'. G1H w/ tension pkr & establish circulation. POOH. G1H w/ 5 1/2" cement retained & set at 1000'. Pump 200 sxs class "C" neat cement. Cement below retained w/ 175 sxs cement. Pull out of retained & spot remaining 25 sxs cement on top of retained. Pull up & reverse clean. Pull bgs to 240' from surface.
5. Spot 25 sxs class "C" neat cement surface plug. Cut off csg strings 3' below restored ground. Cover wellbore w/ cement cap w/ a 2' diameter

18. I hereby certify that the foregoing is true and correct

SIGNED De Finner TITLE Administrative Supervisor

DATE January 12, 1988

(This space for Federal or State office use)

APPROVAL BY Carlsson TITLE CARLSSON RESOURCE AREA

DATE 3 22 88

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Title 18, U.S.C. section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsson & L. L. L.

Queen B No. 1

Pg 2

and 4" thickness. Install P&A marker.

RECEIVED
MAR 23 1988
GCD
HOBBY OFFICE