

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

SUBMITTING TRIBE
(Other instruction
verse side)

Budget Bureau No. 1004-01
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Injection</u>	7. UNIT AGREEMENT NAME <u>MCA Unit</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	8. FARM OR LEASE NAME <u>MCA Unit 512</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, NM 88240</u>	9. WELL NO. <u>#114</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>Unit 5</u> <u>660' FNL & 660' FWL</u>	10. FIELD AND POOL, OR WILDCAT <u>Majamar G-SA</u>
14. PERMIT NO. <u>30-025-00733</u>	11. SEC. T., E., M., OR BLK. AND SURVEY OR AREA <u>Sec. 28, T17S R32E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(Other) Cement Squeeze CO₂ Channel X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATION. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

1. MIRU. NU BOP. POOH w/2-3/8" P.C. tubing. Set retrievable bridge plug @ 3672'. Establish pump-in rate.
2. Shoot Squeeze perfs. (Perf. Spec: Gun OD 1-1/4", 180 phase, 0.30" EHD, TTP - 4.50". Dump 100 lbs sand on top of plug. Perf. 3647'-3648' w/2 JSPF. POOH.
3. Cement Squeeze 4" csg. w/50 sacks of Class "H". SION 2 days.
4. Drill out cement and test Squeeze holes. GIH w/3-3/8" bit, 4" scraper, DC's & 2-3/8" workstring. Drill out and test to 2000 psi.
5. POOH w/retrievable bridge plug and 2-3/8" workstring
6. Return to injection.

For further technical information call Barry Schneider at 397-5893.

18. I hereby certify that the foregoing is true and correct

SIGNED W.W. Baker W.W. Baker TITLE Administrative Supervisor DATE June 30, 1989

(This space for Federal or State office use)

APPROVED BY Shannon Shaw FOR: Shannon Shaw DATE 7-24-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

JUL 31 1989

OCB
MOBBS OFFICE