

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI. DATE
(Other instructions, if re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. NAME OF OPERATOR Conoco Inc.	3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 660' FWL - Unit Letter E	5. LEASE DESIGNATION AND SERIAL NO. LC-057210X	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME MCA Unit	8. FARM OR LEASE NAME MCA Unit Bldg 02	9. WELL NO. 153	10. FIELD AND POOL, OR WILDCAT Maljamar C-SA	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 28-17S-32E	12. COUNTY OR PARISH Dea	13. STATE NM
14. PERMIT NO. 30-025-00735	15. ELEVATIONS (Show whether DF, RT, CR, etc.)											

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Current to Cased Hole

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU on 5/2/88. Clean out & jet wash to 3837'. Mill out from 3839'-3952'. Spot 15% HCL from 3500'-3824'. Spot 30 bbls resin pack from 3560'-3824'. Drill out 3740'-3824'. Drill to 3969'. Set liner at 3969'. Empd 85 sks of 50/50 Pozmix class "C" cement. Squeeze TOH w/50 sks Pozmix. Drill out cement from 2703'-2874'. Drill out float collar to PBTO. G/H w/4 1/2 tie back & cement w/70 sks class "C" cement. Drill out cement from 2817'-83'. Ran GR-CBL-CCL. Perf 7th zone from 3870'-3950'. Acidize w/49 bbls 15% HCL-NE-FE. Trac 7th zone. Perf 6th zone from 3770'-3800' w/1 spf. Acidize w/30 bbls. Run producing equipment & place on production. Work completed on 6/24/88.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE July 14, 1988

(For Bureau or Federal or State office use)

APPROVED

COMMISSIONERS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

Jul 27 1988

*See instructions on Reverse Side

CARLSBAD, NEW MEXICO

This form, when filled out, makes it a crime for any person knowingly and willfully to make to any department or agency of the BLM-Carlsbad (NMX) (1) False or fraudulent statements or representations as to any matter within its jurisdiction.