

UNITED STATES OF AMERICA
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Injection Well</u>	7. UNIT AGREEMENT NAME <u>MCA Unit</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	8. FARM OR LEASE NAME <u>MCA Unit Bly 3</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. WELL NO. <u>207</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface</u> <u>660' FSL & 660' FEL - Unit Letter P</u>	10. FIELD AND POOL, OR WILDCAT <u>Maljamar G-SA</u>
14. PERMIT NO. <u>30-025-00746</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>28-17S-32E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☒ <u>Convert to Cased Hole</u>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started on 2/29/88. MIRA. Test csg to 2000psi. Drill out & jet wash to 4103'. Run open hole caliper & log profile. Spot 28 bbls of 15% HCL-NE-FE acid from 3870'-4094'. Spot resin pack. Tag top of resin at 3992'. Spot add'l 40 bbls of resin pack. Tag at 3869'. Drill out resin pack from 3869'-3965'. & from 3930'-3969'. Formation & resin from 3969'-4015'. Resin pack from 4015'-4125'. G1H w/washover shoe to 4131'. Mill to 4137'. Drill out from 4140'-4170'. Circ clean. Pump 15 sacks of 16.4" class "H" cement. Tag top of cement at 4082'. Drill out cement & formation to 4098' & all formation to 4140'. Underream from 3860'-3993'. Run fiberglass liner to 4168'. Set w/125 sacks of 50/50 poz mix class "C" cement. Circ cement to 4059'. Ref w/2' spf at 3805'-4142'. Test Htg to 2000psi. Rig down.

18. I hereby certify that the foregoing is true and correct

SIGNED DF FINNEY TITLE Administrative Supervisor DATE May 19, 1988

(This space for general or State office use)

ACCEPTED FOR RECORD

APPROVAL OF _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

JUL 8 1988

*See instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

Title 18 USC Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) Oxy (1) FPCO (1) File

11

RECEIVED

JUN 11 1988

CDP
HOBBS OFFICE