

UNITED STATES OF AMERICA
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUBMIT IN TRI
Other Instructions
DATE

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different test hole.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <i>MCA Unit Bly 2</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. WELL NO. <i>112</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>660' FNL & 660' FNL - Unit Letter A</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljamar C-SA</i>
14. PERMIT NO. <i>30-025-00752</i>	11. SEC., T./E., M., OR BLK. AND SURVEY OR AREA <i>29-17S-32E</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☒ <i>Convert to Cased Hole</i>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU. POOH w/pods & pump. Clean out & jet wash to 4070'. Run G-R-OH caliper from 3500' - 4069'. Run csq scraper. Run 5 1/2" csq to 4069'. Set w/150 sxs sc/sc pozmix class 'C' cement. Tag cement at 3295'. Drill out to 3332 (TOL) Test liner top to 2000 psi. Drill out cement to 3347'. Drill out landing collar from 4024' - 65'. Perf 9th zone from 4000' - 4040'. Acidize & scale inhibit. Perf Upper 7th 3901' - 3095'. Acidize w/30 bbls 15% acid. Sand frac 7th zone 3823' - 3931'. Perf 6th zone 3690' - 3797'. Acidize & sand frac. Run producing equipment & place well on production

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* *D. FINNEY*

TITLE *Administrative Supervisor*

DATE *August 15, 1988*

(This space is for Federal or State office use)

APPROVAL OF
COMMISSIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See instructions on Reverse Side

SJS