

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Injection</u>	7. UNIT AGREEMENT NAME <u>MCA Unit</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	8. FARM OR LEASE NAME <u>MCA Unit Bly 2</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. WELL NO. <u>154</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface</u> <u>1980' FNL & 660' FEL - Unit Letter H</u>	10. FIELD AND POOL, OR WILDCAT <u>Maljamar C-5A</u>
14. PERMIT NO. <u>30-025-00753</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>29-17S-32E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) <u>Convert to Cased Hole</u>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Clean out open hole. Bridge plug at 3634'. Mill BP to 4065'.
"Puddle Pack" OH from 3703'-4064'. Tag resin top at 3678'. PB at 3646' w/ Cal Seal. Shoot squeeze holes at 3643'. Squeeze csq shoe w/ 75 ss. Drill out squeeze & resin. Fell out of resin coated sd at 3703'. Re-"puddle-packed" w/ 15 lbl. PB w/ pea gravel to 3660'. Re-squeeze csq w/ 150 ss. Drill out cement & wash out pea gravel. Re-"puddle-pack" w/ 20 lbls. DO resin matl. Kick out of hole at 3828'. Tried to go in old hole, could not. Tried to continue dirty new hole, hit junk. Plugged back w/ cement. DO in old hole to TD. Underreamed OH & run lines, cmt'd w/ 130 ss. DO lines, ran CBL & perf from 4010' - 3758'. Run injection equipment.

18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>July 14, 1988</u>
The space for Federal or State office use)		
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>[Signature]</u>
CONDITIONS OF APPROVAL, IF ANY:		

*See instructions on Reverse Side