

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other Instructions
verse side)

SECRET
Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. NAME OF OPERATOR Conoco Inc.	3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FS & 1980' FW - Unit Letter K	5. PERMIT NO. 30-025-00754	6. ELEVATIONS (Show whether DF, RT, GR, etc.)	7. UNIT AGREEMENT NAME MCA Unit	8. FARM OR LEASE NAME MCA Unit Bty 2	9. WELL NO. 170	10. FIELD AND POOL, OR WILDCAT Maljamar C-SA	11. SEC., T., & R., OR BLK. AND SURVEY OR AREA 29-17S-32 E	12. COUNTY OR PARISH Lea	13. STATE NM
--	------------------------------------	--	--	-------------------------------	---	------------------------------------	---	--------------------	---	---	-----------------------------	-----------------

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)	☒ Convert To Cased Hole		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started on 8/2/88. MIRA. Jet wash & CO to TD. Ran OH caliper 3482'-4058'. Spot 30 bbls of 15% HCL-NE-FC-access formation. Rmpd 50 bbl resin pack. G1H w/ bit & tag resin pack at 3414'. DO to 4058'. Deepen well to 4150'. Ran 5 1/2" csg 3263'-4157'. Set w/150 sxs 50/50 pozmix class "C" cement. Tag cement 3037' & DO to TOH at 3263'. G1H w/ tie-back & set w/180 sxs class "C" cement. Tag cement at 3184' & DO to 3315'. DO FC to 4157'. Perf 9th zone w/2 ssp 4055'-4096' & acidize. Perf 7th zone w/2 ssp 3916'-4023'. Acidize & sand frac 7th zone. Perf 6th zone w/1 ssp 3792'-3839' & acidize. Run producing equipment & place on production. Work completed on 9/8/88

I hereby certify that the foregoing is true and correct.

[Signature]
Name of State official

TITLE Administrative Supervisor

DATE October 17, 1988

ACCEPTED FOR RECORD

DATE OF APPROVAL IF ANY

TITLE

DATE

OCT 31 1988

(See instructions on Reverse Side)

SJS
CARLSBAD, NEW MEXICO

RECEIVED

NOV 2 1988

OCD
HOBBS OFFICE