

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other: Injection

2. Name of Operator
CONOCO INC.

3. Address and Telephone No.
10 DESTA DRIVE, STE 100 W, MIDLAND, TX 79705 (915) 686-5494

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980 FSL 2 460 FWL
Unit letter L, Sect. 29, T19S, R32E

5. Lease Designation and Serial No.
LC-029410A

6. If Indian, Alutian or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. By 2
MCA Unit, No. 169

9. API Well No.
30-025-00755

10. Field and Pool, or Exploratory Area
Maljawan (G-SA)

11. County or Parish, State
Lea, nm

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
☐ Notice of Intent	☐ Abandonment
☒ Subsequent Report	☐ Recompletion
☐ Final Abandonment Notice	☐ Plugging Back
	☐ Casing Repair
	☐ Altering Casing
	☒ Other <u>Do cmt.</u>
	☐ Change of Plans
	☐ New Construction
	☐ Non-Routine Fracturing
	☐ Water Shut-Off
	☐ Conversion to Injection
	☐ Dispose Water

(Note: Report results of multiple completions on Well Completion or Resumption Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and estimated and true vertical depths for all markers and zones pertinent to this work.)

MIRU. RH Wireline - install pmp through plug in R nipple. Install BOP stack. Ret pmp through plug in "R" nipple. Install BOP stack. Ret pmp through plug. Ret seal assembly. Circ 10# brine. B1H w/2 3/8 bit. Jagged TOC at 3796. Do to 3850. Do conventional to 3877 - fell through. Washed to 3927. Thudded up w/15.2#. Wait 30 min - well died. Cont in hole to 4060. Pull up to liner top. B1H w/seal assy. IPC tbg. Displace mud w/pkr fluid. Tst tbg - tst backside 500# for 30 min - HELD. Ret blanking plug. Ret to inj. 9-3-91

FOR FILING
Adm
MAY 11 1991

14. I hereby certify that the foregoing is true and correct

Signed Christine L. Neff Title ADMIN. ASSISTANT EL PASO, NEW MEXICO

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
 Conditions of approval, if any:

