

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Federal Fee ☐  
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Injection Well</u>	7. Unit Agreement Name <u>MCA Unit</u>
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>MCA Unit</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. Well No. <u>169</u>
4. Location of Well UNIT LETTER <u>L</u> , <u>1480</u> <sup>1980</sup> FEET FROM THE <u>South</u> LINE AND <u>660</u> <sup>330</sup> FEET FROM THE <u>West</u> LINE, SECTION <u>29</u> TOWNSHIP <u>17S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat <u>Maljamar C-5A</u>
15. Elevation (Show whether DF, RT, GR. etc.)	12. County <u>Dea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Convert to Cased Hole</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work started on 3/2/88. MURU. Test csq to 2000 psi. Clean out & jet wash to TD. Resin pack open hole 3750' - 3933'. Drill out & underreamed to TD. Run liner 3424' - 4049'. Run CR-CBL. Perf 3767' - 3866' w/ 1 jspF 6<sup>th</sup> zone; 7<sup>th</sup> zone 3896' - 3927' w/ 1 jspF and 3951' - 86' w/ 2 jspF; 9<sup>th</sup> zone 4014' - 23' w/ 1 jspF and 4023' - 4058' w/ 2 jspF. Acidized & return to injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] D.F. FINNEY TITLE Administrative Supervisor DATE May 18, 1988

APPROVED BY [Signature] JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE MAY 26 1988

CONDITIONS OF APPROVAL, IF ANY:

Conoco-Hobbs (3) File