SUBMIT IN TRIPLICATE    Type of Well	OVED 1004-0/35CO 31, 1993 and Serial No. 29410A Tribe Name	· •••
Second Processor of Competed Operations (Clearly state all pertinent delates, and give pertinent design, or indicationally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertnent delated and shut in.    Second Processor of Competed Operations (Clearly state all pertnent delates, and give pertnent delate, and good. NDBOP, NUVH, latch onto packer and shut in.    Second Processor of Competed Operations (Clearly state all pertnent delates, and give pertnent delates and zones pertnent to this work.)*    Second Processor of Competed Operations (Clearly state all pertnent delates, and give pertnent delates, and zones pertnent to this work.)*    Second Processor of Competed Operations (Clearly state all pertnent delates, and give pertnent delates, including estimated deate of statificing may proposed work. If directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertnent to this work.)*    HOBBS INSPECTION OFFICE	nent Designation	ion
TYPE OF SUBMISSION  TYPE OF ACTION    Notice of Internt	ourg San An State	
Notice of Intent  Abandonment  Recompletion  New Construction  Non-Routine Fracture  Casing Repair  Water Shut-Off  Attering Casing  Conversion to Inject  Completed Dispose Water  Replace bad tubing, run MIT  (New Report results of motions of Recompletion or Recompletion		<del></del>
Recompletion   New Construction   New Construction   New Construction   Plugging Back   Non-Routine Fracture   Water Shut-Off   Casing Repair   Water Shut-Off   Other   Dispose Water   Replace bad tubing, run MIT   (Note: Report results of multiple of Completion or Recompletion or Reco	<del></del>	<del></del>
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*  1-3-96 Set plug in tubing at 3054'. Bled tubing and casing off, circulate well after getting off on-off tool. POOH w/ tubing, did  1-4-96 RIH testing tubing. Found bad joint 45 joints from surface. Replaced bad joint, test remaining tubing in hole. Release Pressured tested well to 500# and ran a chart. Held good. NDBOP, NUWH, latch onto packer and shut in.  HOBBS INSPECTION OFFICE	ction	
98. WEO BY THE SHOPE HOBBS INSPECTION OFFICE	id not find he	
ACCEPTED FOR RECORD DATE 3-11-56	GARI AREZ AS	HAR 1 11 35 AH 196
SIGNATURE URB	·	O,

Approved by Title Date Conditions of approval, if any

Ann E. Ritchie REGULATORY AGENT

Title

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

MP

2-26-96

14 I hereby certify that \$

