

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instruction
verse side)

DATE
) re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <i>MCA Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA Unit sty 2</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. WELL NO. <i>158</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <i>At surface</i> <i>1980' FNL & 6.00' FWH - Unit Letter E</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljamar G-SA</i>
14. PERMIT NO. <i>30-025-00761</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>29-17S-32E</i>
15. ELEVATIONS (Show whether DP, RT, GR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETION	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other) <i>Convert to Cased Hole</i>	☒		☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started on 6/30/88. MIRU. POOH w/ rods & pump. Clean out & jet wash from 3447'-3943'. G/H w/ Cut-rate shoe. Cut to 3973'. Run caliper log from 3400'-3962'. No resin pack needed. Run 5 1/2" lined to 3970'. Cement w/ 200 sacks of 50/50 Pozmix "C" cement. Drill out to 3194'. Drill out cement to 3970'. Perf 9th zone w/ 1 jspF 3958'-61'. Acidize w/ 15% HCL-NK-FE. Perf 7th zone 3815'-3918'. Acidize & sand frac. Perf 6th zone w/ 1 jspF from 3747'-3781' and acidize. G/H w/ rods & pump. Rig down & place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* DE FINNEY

TITLE Administrative Supervisor

DATE 9/13/88

This space for Federal or State office use)

APPROVAL OF
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

SEP 19 1988

SJS

*See instructions on Reverse Side

CARLSBAD, NEW MEXICO

Section 10-1 of the Department of the Interior, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (11) 1004 (1) FPO (1) L.C.